



**CIVIL AVIATION COMMITTEE
OF THE REPUBLIC OF ARMENIA**

SAFETY BULLETIN N 1

Date: 18.11.2022

Subject: Rejected take-off due to discrepancy between air speed indication

Area of Concern: Commercial air operations

Distribution: All AOC holders of the Republic of Armenia

Discussion: "FLYONE ARMENIA" airline's A319 Reg. ER-00002 aircraft (FIE 475 EVN-IST) executed rejected take-off due to discrepancy between air speed indication with more than 40 knots at 14:35 (UTC)/18:35 local time (GMT +4) on 08.07.2022.

On 11th of July 2022, technical inspection was conducted by the Investigation Commission, in particular by Airworthiness inspector from Civil Aviation Committee of the Republic of Armenia, Technical Director of "FLYONE ARMENIA" LLC, B2 Category engineer of "FlyOne S.R.L" and independent expert, B2 engineer from "Cross technics" LLC.

By studying all circumstances and parameters, the Investigation Commission concluded that the incident happened due to the blockage of 3 small dried deposit in the F/O pitot.

Recommendation: The Investigation Commission recommends all AOC holders to:

- include Unreliable Speed Indication in the nearest training session on FFS.

Requirements: Provide evidence of the recommendation.

MIHRAN KHACHATRYAN

CHAIR OF CIVIL AVIATION COMMITTEE

